

## BMW brake warning lamp reset

On some vehicle, brake warning lamp will illuminate after brake pads wear or/and replacement. The best, easiest way to reset it is to use a scanner!

The following is the method to reset brake warning lamp on some BMW new 7 series models (E65) with Launch X-431.

Connect X431 to the car and power on, after download software and initialization finished, please select Chassis → Coding and programming → Maintenance → E65 Series → CBS Reset 1, see Fig.1, Fig.2.




Fig.1




Fig.2

After you click CBS reset 1 as Fig.2, available functions menu display as Fig.3. Select “Front brake” or “Rear brake” according to you have replaced. If the availability present is more than 80%, warning information will be pop up as Fig.4. You can choice to reset or not. If availability is less than 80%, reset will be done automatically without any warning.




Fig.3




Fig.4

Note: Please troubleshooting DSC and erase all DTCs stored before performing this function.