

How to reset the service indicator of Volkswagen vehicle

(2004-3-29)

I. Reset with scan tool

1. For A6, B5, Bora and Polo vehicles, do the following steps:

- a) Connect X-431 scan tool.
- b) Turn on the ignition switch.
- c) Select "Volkswagen".
- d) Enter the instrument panel system
- e) Select function "Adaptation_i± and enter "02" for channel No., and then Click [OK]
- f) Enter "00000" for matched data and then click [OK].
- g) Exit

2. Select the function "OIL RESET" in X431 Volkswagen diagnostic program to reset the service indicator.

II. Manual resetting of service indicator for Audi vehicle

1. TT 1998-1999

Service indicator

- a) Press and hold button A
- b) Turn ON the ignition switch
- c) "SERVICE" or "SERVICE IN XXXXMI" is displayed on the odometer.
- d) Release button A.
- e) Turn button B to the right so as to reset the meter.
- f) "SERVICE IN XXXXMI" will be displayed on the odometer.
- g) Turn OFF the ignition switch.

2. TT 2000--

If the vehicle is equipped with the maintenance-free instrument panel, proper scan tool must be used for service reset.

If the instrument panel requires regular maintenance, use the following procedure to manually reset it:

- a) Press and hold button A.
- b) Turn ON the ignition switch.
- c) Release button A
- d) "SEVICE" or "SERVICE IN XXXXMI" is displayed on the odometer
- e) Turn button B to the right so as to reset the meter.
- f) "SERVICE IN 10000MI" will be displayed on the odometer.
- g) Turn OFF ignition switch.

3. A2 2000-

A6 2000-

If the vehicle is equipped with the maintenance-free instrument panel, proper scan tool must be used for service reset.

If the instrument panel requires regular maintenance, use the following procedure to manually reset it:

- a) Press and hold button A.
- b) Turn ON the ignition switch
- c) "SERVICE" or "SERVICE IN XXXXMI" is displayed on the LCD screen
- d) Release button A
- e) Press button B to reset the display. "SERVICE IN 10000MI" will be displayed on the LCD screen.
- f) Turn OFF the ignition switch.

4. A6 1997-1999

Reset the oil service indicatorλ.

- a) Press and hold button A.
- b) Turn ON the ignition switch
- c) Release button A
- d) "OEL" or "OIL" will be displayed on the LCD screen
- e) Press and hold button "B" until the character is erased and "-----" is displayed on the LCD screen.

Reset the INSP indicatorλ.

- a) Press and hold button A
- b) Turn ON the ignition switch
- c) Release button A
- d) Press button "A" ,and then release it.
- e) "INSP" will be displayed on the LCD screen
- f) Press and hold button "B" until the character is erased and "-----" is displayed on the LCD screen.
- g) Follow the above mentioned steps to erase the displayed character "OEL" or "OIL" if necessary.

5. POLO 1999-

POLO CLASSIC/ESTATA 1999-

Reset the oil service indicatorλ.

- a) Press and hold button A.
- b) Turn ON the ignition switch
- c) Press and hold button "A" until the character is erased and "-----" is displayed on the LCD screen.

d) Release button A

e) Turn OFF the ignition switch

f) Follow the above mentioned steps to erase the displayed character "OIL" if necessary.

Reset the INSP indicator.

a) Press and hold button A.

b) Turn ON the ignition switch

c) Press and hold button "A" until the character is erased and "-----" is displayed on the LCD screen.

d) Release button A

e) Turn OFF the ignition switch

f) Follow the above mentioned steps to erase the displayed chara